

# GOLDMORR CASE STUDY

## Home Water Loss

## No Need To Automatically Rip Out Drywall!

### PROJECT BY COMPETITOR:

A contractor was hired to perform repairs in a home that suffered a water loss in the kitchen area from a plumbing leak. As the contractor started to tear out the wet vinyl flooring, they discovered that mold was present beneath the vinyl flooring and aborted the job since their insurance company made it very clear that they had no coverage for mold and would discontinue coverage if they ever learned of them touching a mold job. The owners of the property were referred to Goldmorr.

### GOLDMORR PROJECT INSPECTION:

At the conclusion of my initial inspection of the kitchen, the homeowner asked if I could also take a look at her master bathroom on the opposite side of the house, since she said "I think I might have a mold problem." To my surprise, the walls and ceiling were completely covered with mold staining. I proceeded to inspect the room and there was no evidence of a water loss and no wet building materials in the room (base of walls and flooring were completely dry). However, there was no exhaust fan or even a window in the bathroom. Every day the homeowners would use the shower. The humidity would spike, allowing a thin layer of surface mold to form. Then the surfaces would dry out. This happened day after day until many layers of surface mold developed. ***This was the perfect job for a non-invasive Goldmorr treatment!***

### GOLDMORR STEPS PERFORMED:

We micro-cleaned the walls and ceiling with our GM6000 mold stain remover followed by our non-mechanical air scrubbing treatment using our GM2000 fogging agent to clean the air of the unseen mold spores. Instead of lengthy traditional methods, this process was ***performed in a quick half-day turn around.***

### GOLDMORR RESULTS:

The customer was amazed with the results and completely satisfied!



**Goldmorr  
removed the  
visible and  
invisible mold!**



[www.goldmorrusa.com](http://www.goldmorrusa.com)