

**SAMPLE PORTION OF THE REPORT THAT INCLUDES AN EASY TO READ AND EXPLAIN TO CUSTOMER THE RESULTS AND IMPROVEMENT IN THEIR AIR QUALITY ROOM BY ROOM**

| <b>BEFORE - particle counts per cubic meter and analysis</b> |         |         |        |           |
|--|---------|---------|--------|-----------|
| Location   | ≥0.5 μm | ≥5.0 μm | Time   | IAQ Level |
| Bedroom 2  | 5939575 | 219787  | 1m, 0s | 9         |
| Master Bedroom   | 2159010 | 72084   | 1m, 0s | 8.5       |
| Bedroom 1  | 2479151 | 74204   | 1m, 0s | 8.5       |
| Living Room  | 3835689 | 343462  | 1m, 0s | 9.5       |
| Outdoors   | 2649823 | 31802   | 1m, 0s | 8.5       |
| Kitchen  | 3171731 | 200000  | 1m, 0s | 9         |

**FAIL**

| <b>AFTER - particle counts per cubic meter and analysis</b> |         |           |         |           |        |           |
|---|---------|-----------|---------|-----------|--------|-----------|
| Location  | ≥0.5 μm | Reduction | ≥5.0 μm | Reduction | Time   | IAQ Level |
| Bedroom 2   | 403886  | 93.2%     | 14487   | 93.4%     | 1m, 0s | 8         |
| Master Bedroom  | 235689  | 89.1%     | 1413    | 98.0%     | 1m, 0s | 7.5       |
| Bedroom 1   | 214487  | 91.3%     | 3886    | 94.8%     | 1m, 0s | 7.5       |
| Living Room   | 436042  | 88.6%     | 13427   | 96.1%     | 1m, 0s | 8         |
| Outdoors  | 620848  | 76.6%     | 9187    | 71.1%     | 1m, 0s | 7.5       |
| Kitchen   | 326855  | 89.7%     | 9893    | 95.1%     | 1m, 0s | 8         |

**PASS**